



Dangerzone Installation Gap:

Mould Threat!

Cut out and be shocked: The installation gap between ceiling and hatch of attic stairs sums up to a hole as big as on this sheet!
(This example displays a surrounding gap of only 1-cm width for a ceiling opening of 110x60 cm)



Weak point: Installation gap. If not sealed airtight, warm and humid air escapes through this large "hole" into the cold attic.
Alarming consequences: Heat loss and wasting energy are expensive. Mould growth and structural damage are dangerous!
Tested and certified solution: The ceiling connection system (combination of sealing tape and insulating braid) seals the gap.

Attic stairs with thermal protection:
**Sealing system for airtight
installation always included!**

wellhöfer
TREPPEN AUS WÜRZBURG



Wellhöfer Treppen GmbH & Co. KG

Max-Mengeringhausen-Str. 1
97084 Würzburg, Germany

Tel. +49 (0)931 / 614 05-0

Fax +49 (0)931 / 614 05 71

www.wellhoefer.de

info@wellhoefer.de



Dangerzone Installation Gap: Fire Threat!

Cut out and be shocked: The installation gap between ceiling and hatch of attic stairs sums up to a hole as big as on this sheet!
(This example displays a surrounding gap of only 1-cm width for a ceiling opening of 110x60 cm)



Weak point: Installation gap. It must be completed exactly as in the fire protection test. Filling it completely?! With gypsum?! With mineral wool?!
Alarming consequences: If the gap is not fire-retardant, flames penetrate this large "hole" and the dangerous chimney effect occurs!
Tested and certified solution: The ceiling connection system (combination of intumescent strips and fire protection braid) makes the gap fire-retardant.

Attic stairs with fire protection:
**Connection system for fire-retardant
installation** always included!

wellhöfer
TREPPEN AUS WÜRZBURG



Wellhöfer Treppen GmbH & Co. KG

Max-Mengeringhausen-Str. 1
97084 Würzburg, Germany

Tel. +49 (0)931 / 614 05-0

Fax +49 (0)931 / 614 05 71

www.wellhoefer.de

info@wellhoefer.de